





WWW.NORTHERNDOCKSYSTEMS.COM







### **WORK ORDER #: W060924**

Address: 415 Ambassador Dr., Mississauga ON L5T 2J3

Toll-free: 1 (866) 601-1758 | F: (905) 625-0187 | E: service@northerndocksystems.com

# **EMERGENCY**SERVICE

#### **Customer Information**

XYZ Company - Headquarters 495 Main Street Toronto, L7H 8D3 ON, Canada

**Phone Number** 416-975-6245

## **Service Location**

XYZ Company - Woodbrigde 789 Queen Street Woodbridge, L4L 7H9 ON, Canada

Contact Joe Smith

#### **Service Details**

Created	2/28/2020 12:31 PM	Last Updated	3/2/2020 7:30 AM
Туре	Local Service	Priority	
Status	Open - Completed	Last Visit Date	3/2/2020 7:30 AM
Next Step	To be invoiced	Field Specialist	Justin Brum
Primary Incident Type	Door	Signed By	Joe Smith
Customer Asset		P.O #	CK022954-014
Scope of Work	Main Door # 3 The main bracket that connects the overhead door to the opener snapped.		

## **Execution Notes**

	Details	Content
Created On:	Bay Door # 3	
2/28/2020		
2:14 PM	<ul> <li>Found hook up arm snapped, hooked up on</li> </ul>	
	trolley is jammed in the operator	
Created By:	<ul> <li>Cable is off the drum, and door is stuck.</li> </ul>	
Justin Brum	<ul> <li>Left site to get a new arm from supplier,</li> </ul>	
	then returned to site with part	
	<ul> <li>Unjammed the traveler, reset the top limit on</li> </ul>	
	the operator	
	<ul> <li>Put cable back on right side drum, adjusted</li> </ul>	
	the tension on the springs.	
	<ul> <li>Attached new hook up arm and tested the</li> </ul>	

	door several times • Door is ok • Completed	
Created On: 2/28/2020 3:41 PM		VIM
Created By: Justin Brum		
Created On: 2/28/2020 3:50 PM	Before	
Created By: Justin Brum		
Created On: 2/28/2020 3:50 PM	New arm	
Created By: Justin Brum		
Created On: 2/28/2020 3:50 PM	Door # 3	
Created By: Justin Brum		