



Dock Seals and Steel Face Dock Bumpers Good Water Warehouse

Calgary, AB



Project Overview

The dock seals at Good Water Warehouse in Calgary had worn down prematurely. This Calgary warehouse reached out to Northern Dock Systems to replace them.

After completing a site check to get the correct measurements, our Project Manager determined that the dock seal was worn down prematurely because of the crushed and worn dock laminate dock bumpers. As a result, there was a loss of projection and the dock seal was over-compressed. Additionally, there was a void behind the dock bumper which is why the old bumpers were being crushed.

In order to prevent the new dock seals from getting over-compressed, we resolved the underlying issue of filling the void. So the new steel face dock bumpers would not be warped from the void over time. Steel face dock bumpers have a floating steel faceplate that extends the bumper's lifespan. They can withstand frequent impacts in heavy traffic situations.

The new adjustable head curtain dock seal has 4" wear pleats to provide three layers of protection from wear and tear. At the same time, the yellow guide strip makes it easier for drivers to back into the position.

Additionally, we added corner flaps that cover the gap around the bumpers. This Calgary warehouse has already seen the difference this makes because it has blocked snow from coming in through the doors.

- ✓ Improve safety
- ✓ Tight-seal
- ✓ Workplace productivity
- ✓ Indoor comfort
- ✓ No white light
- ✓ Pass audits
- ✓ Energy-saving
- ✓ Protects from damage

Featured Products

[Adjustable Head Curtain Dock Seals \(201\)](#)



[Steel Face Dock Bumpers](#)



EQUIPMENT INSTALLATION



ENERGY SAVING SOLUTIONS