

#### WWW.NORTHERNDOCKSYSTEMS.COM

### 

FACEBOOK

# WORK ORDER #: WO140194



Address: 4416 5 St NE #2, Calgary, AB T2E 7C3

## **Customer Information**

Calgary Centre Ave SE Calgary, T2E 0A8 Alberta, Canada

### Service Location

Calgary Centre Ave SE Calgary, T2E 0A8 Alberta, Canada

**Phone Number** 

#### Contact Miro

#### **Service Details**

Created	2/3/2025 2:36 PM	Last Updated	2/27/2025 8:48 AM
Туре	Local Service	Priority	
Status	Completed	Last Visit Date	2/21/2025
Next Step	No Action Required – internal	Field Specialist	Layne
Primary Incident Type	Pedestrian Door Service	Signed By	Miro
Customer Asset		P.O #	4501713273
Scope of Work	<ol> <li>1) Exterior door next to dock 12 needs replacement closer.</li> <li>replacement to stronger unit than what is currently on door as often hovers with air pressure at intermittent times. Closer and new hinges.</li> <li>2) Cooler room door needs replacement closer to match current door.</li> </ol>		

## **Execution Notes**

	Details	Content
Created On: 2/25/2025 10:46 AM Created By: Layne	Hinges before replacement.	
Created On: 2/25/2025 10:46 AM Created By: Layne	New hinges	
Created On: 2/25/2025 10:46 AM Created By: Layne	Replaced close with new LCN 4040 closer	
Created On: 2/25/2025 10:48 AM Created By: Layne	Exterior of door after replacement of hinges showing margins. Door fits and functions well.	

Created On: 2/25/2025 10:48 AM Created By: Layne	Sargent before replacement, oil leaked and slamming door.	
<b>Created On:</b> 2/25/2025 10:50 AM <b>Created By:</b> Layne	Replaced Sargent closer, tested working well. Does not slam	
<b>Created On:</b> 2/25/2025 10:56 AM <b>Created By:</b> Layne	Conclusion: Work completed on exterior door next to dock 12. Replaced closer and replaced 3 hinges. Door closing consistently and closes smoothly.Completed replacement Sargent 1431 on cooler door. Door no longer slamming, working appropriately.	