





Curtain Style Foam Pad Dock Seal Apotex Inc.

Etobicoke, ON



Project Overview

Apotex Inc. in Etobicoke had old and worn dock seals. The gaps around the dock seals were allowing water and rain to enter the building. In addition, cold drafts made the area uncomfortable for employees while the rain entering the building made for unsafe conditions. Finally, the overall look of the building needed improvement.

The new [curtain style foam pad dock seals](#) were quoted and installed on all eight dock positions to seal up any gaps that were there before. Since then the sealed gaps have improved employee safety and satisfaction. Additionally, the overall look of the building has also been improved.

- ✓ Tight seal
- ✓ Improve safety
- ✓ Indoor comfort
- ✓ No white light
- ✓ Energy-savings

Featured Products

[WearTough FC](#)
[Curtain Style Foam Pad](#)
[Dock Seal](#)



- Increase safety for workers
- Ensure product safety



**EQUIPMENT
INSTALLATION**



**ENERGY
SAVING
SOLUTIONS**