





Rolling Steel Door
Valley Ridge Condos

Fort Saskatchewan, AB



Before



Install



After



Install



After

Project Overview

Valley Ridge Condos in Fort Saskatchewan Alberta contacted us to give them a quote to replace the broken spring on one of their two steel roll-up doors.

However, the replacement barrel and spring would take 4-5 months for manufacturing and delivery due to a current shortage. Additionally, the Alberta customer had just installed new operators when the spring broke and was looking for a quick solution.

Northern Dock Systems sourced a replacement [coiling steel door](#) that would take half the time to get delivered and installed. Then, the condo manager approved replacing both coiling steel doors because of the age of both their existing doors.

As a result, NDS was able to quickly deliver and install the replacement [rolling steel doors](#) in half the time. Furthermore, we saved them money by utilizing newly installed operators. Finally by replacing both aging doors, we improved the appearance of their building.

- ✓ Security
- ✓ Durability
- ✓ 50,000 cycles
- ✓ Improve safety

“Extremely happy with the quality of installation and new doors.”
- Kathleen Bruce, Condo Manager

Featured Products

Rolling Steel Door



- Improve safety and security
- Choice of operation (push-up, chain, crank, or motor)

